


SEWING MACHINE TABLE
COMFORT COMPACT
СТОЛ ДЛЯ ШВЕЙНОЙ МАШИНЫ



SYMBOLS



ATTENTION

ВНИМАНИЕ




ASSEMBLY & ADJUSTMENT

СБОРКА РЕГУЛИРОВКА




OPERATION

ЭКСПЛУАТАЦИЯ



INDICATING MARK



ОБОЗНАЧЕНИЕ



EVEN SURFACE

РОВНАЯ ПОВЕРХНОСТЬ

010001 1x	010002 1x	010003 1x	010004 1x
010005 1x	010006 1x	010007 1x	010011 1x
010012 1x	010013 1x	010014 1x	010026 1x
010028 2x	030033 1x		


020003  1x	020004 1x  020005 1x 	020006  1x	1x 020010  L 660
---	--	---	---


3 x 020013 CR 	3 x 020013 CL 
--	---

3 x 020015 DR 	3 x 020015 DL 
--	---

020021 2x 	020034 2x 
---	---


030001  3 * 16 36x	030002  3,5 * 16 20x	030003  6,2 * 50 22x	030033  4,2 * 13 3x	030006  2,9 * 13 2x	
030008  φ4 2x	030009  M4 * 20 2x	030011  φ15 22x	030012  φ18 8x	030013  L = 35 8x	030014  φ15 h12 8x
030015  φ8 * 30 2x	030016  φ8 * 30 2x	030017  φ15 h10 2x	030061  4x M 8	030060  φ8 4x	030031  φ8 s2,5 4x

1x 050004 	1x 050005 	1x  S 4
--	---	--



010002

010001




8

030013



14 020005

1x



030001

2x



010005



010007

13 3x 030011

3x 030003



12

1x 020010

22x

030001

9

8x

030014




8x

030012



11 020003

1x



3x

030033



10

030008 030009











2x


2x

1x

020006








22


2x 030001



1x 020015 DR



010012




010013

030016 20
2x

21
2x 030017

22



1x 020015 DL

030001
2x



010011

19

030015
2x

