

SEWING MACHINE TABLE
COMFORT NEXT
СТОЛ ДЛЯ ШВЕЙНОЙ МАШИНЫ



SYMBOLS



ATTENTION

ВНИМАНИЕ




ASSEMBLY & ADJUSTMENT

СБОРКА РЕГУЛИРОВКА




OPERATION

ЭКСПЛУАТАЦИЯ



INDICATING MARK


ОБОЗНАЧЕНИЕ





EVEN SURFACE

РОВНАЯ ПОВЕРХНОСТЬ

010001	1 x	010003	1 x	010004	1 x
010006	1 x	010007	1 x	010013	1 x
010015	1 x	010023	1 x	010024	1 x
010025	1 x	010026	1 x	010027	1 x
010032	1 x	010038	1 x	010039	1 x
010040	1 x	010043	1 x		

020001 2x 		020002 2x 									
020004 2x 		020005 2x 		2x  020006		1x  020011		1x  020012		020018 4x 	
2x 020013 CR 			2x 020013 CL 			2x 020016 		020021 4x 			
2x 020015 DL 			2x 020015 DR 								

030001 12x  3 * 16	030002 32x  3,5 * 16	030003 18x  6,2 * 50	030033 14x  4,2 * 13	030006 6x  2,9 * 13	030008 4x  φ 4	030038 4x  2,5 * 20
030009 4x  M4 * 20	030011 18x  φ 15	030012 12x  φ 18	030013 12x  L 35	030014 12x  φ 15 h 12	030028 8x  3,9*16	
030015 2x  φ 8 * 30	030016 2x  φ 8 * 30	030017 2x  φ 15 h 10	030061 4x  M 8	030060 4x  φ 8	030031 4x  φ 8 s2,5	

1x050002 	1x050004 	1x050005 
1x050003 		
S41x 		



3

2 x 020004

4 x 030006

4

6x 030013

010001

010004

1

4x 030011

4x 030003

010003

5

6x 030014

6x 030012

010006

2

020001

2 x 030033

6x


2




020002

2 x 030033

6x

* Входит в комплект стола.
Included into table set.






* Входит в комплект стола.
Included into table set.

19


2x 030001



1x 020015 DR

20

1x 050005 4x 030002



19




020015 DL 1x

2x 030001

21

1x 050004 4x 030002




22 4x 030011 4x 030003

25

2x 030017

26

2x 030001




1x 020015 DR

030016 24 2x

23 2x 030015

26



020015 DL 1x

2x 030001

